



# Screw Point Identification Chart



## Sharp Point Types

Twin Thread



A



B



AB



17



## Self-Drill Point Numbers

1



2



3



4



5



## Self-Drill Point With Wings

